

LIBRARY / CED CENTRE

SHORT TERM

- Need Library Sign with arrow. **In progress**
- Need more international symbol of access signage.
- More and consistent signage required overall including tactile signage.
- 2 designated accessible parking spaces required. Previously located in front of building. **In progress**
- Automatic door opener on front door. Ensure sign is visible.
- Door controls should be contrasting color with door.
- Mark swing path of doors opening into corridors or pedestrian traffic.
- Too much stuff in hallway – chairs, plants, brochure rack, etc. One side should be kept free of obstacles. - Done
- Install mats to cut down on glare and place throughout to help with slipping and color contrast. - Done
- Use slip resistant mats where appropriate. - Done
- Need arrows in the hallway showing the way to washrooms – **In progress**
- washrooms should be signed using the international symbol of accessibility including braille and tactile.
- paper towel holder in washroom is too high.
- Install sign on accessible washroom stall
- Need border around urinals or paint wall to show contrast on wall.
- Post exit sign on interior of washroom - Done - Door is contracting color no need for exit sign inside
- Reception Area and Service Counter are not visible - suggested arrows and different color tiles.
- No signage explaining function of service desk.
- No exit signs above main entrance
- Evacuation plan needs to be lowered. **In progress**
- Evacuation instructions need to be larger and updated. Muster area needs to be added. – **In progress**
- Bookcase in library needs to be moved to allow clear sight of fire alarm at that location.
- Fire extinguisher is blocked in program room.
- Access to picnic tables and benches is on grass – may need to be relocated.
- Suggested darker posts in Library – Currently same color as the walls. – Done – No need for action - posts are blocked by bookcases and desks.

MEDIUM TERM

- Walkways could be contrasting color to make more visible.
- It was suggested that mats would help with glare and could be used to connect entire walkway.
- Handrail would be helpful in the hallway
- Counter does not provide required knee space.

LONG TERM

- Ramp is not required, but could be installed at back emergency exit. 4 inch drop.
- Handrails would be helpful outside along walkway and hallways.
- Only very small curb ramp in front of building, leading to main door.
- Install door sensors to detect users approaching
- washroom door is too small
- washroom walls, doors, floors, etc. should be contrasting color Internal dimension between walls are not 67 in. to 98 in.
- There is no clear turning diameter of at least 67 in. in washroom
- Washroom - Check to ensure clearance of 67 in. between the inside face of an in-swinging entrance door and the outside face of an adjacent stall.
- Washroom - Check to ensure clear floor space of at least 67 x 67 in. in front of the accessible stall.
- No privacy in washroom for self-catheterization
- Visual fire alarm would be beneficial
- Power plug-ins in public areas of the building should be tamper proof.
- manual fire and emergency alarm controls are mounted too high