

Assessment of Playgrounds

Brass Hill Playground

SHORT TERM

- Waste receptacle should be color-contrasted with surroundings. In Progress
- Picnic tables on site are not accessible. – New accessible tables have been built- Done
- No clear accessible path up to the table – Locations will be taken into account when tables are placed in the spring. - Done
- Exploring possibility of purchasing accessible swings. In Progress

MEDIUM TERM

- No sensory components, such as gardens or planters
- No designated parking area

LONG TERM

- No ground level stand-alone features, such as spring rockers or teeter-totters

Barrington Playground

SHORT TERM

- Waste receptacle should be color-contrasted with surroundings. In Progress
- Waste receptacles are not accessible. Location will be taken into account with units are placed onsite in the spring.
- Picnic tables on site are not accessible.- New accessible tables have been built- Done
- No clear accessible path up to the table. – Locations will be taken into account when tables are placed in the spring. – Done
- Exploring possibility of purchasing accessible swings. In Progress

MEDIUM TERM

- No clearly defined accessible entrance
- No sensory components, such as gardens or planters
- No designated parking spaces

LONG TERM

- No ground level stand-alone features, such as spring rockers or teeter-totters

Sherose Island Playground

LONG TERM

- Waste receptacle should be color-contrasted with surroundings. **- In progress**
- Picnic tables on site are not accessible.- New accessible tables have been built- Done
- No clear accessible path up to the table. – Locations will be taken into account when tabled are placed in the spring. – Done
- Exploring possibility of purchasing accessible swings. **In Progress**

MEDIUM TERM

- No sensory components, such as gardens or planters
- 1 accessible parking space requires repainting

LONG TERM

- Walkway leading to playground requires attention (uneven surface, narrow, directional signs required from parking lot, surface blends with surroundings)

South Side Playground

SHORT TERM

- No waste receptacle on-site – In progress
- Picnic tables on site are not accessible.- New accessible tables have been built- Done
- No clear accessible path up to the table. – Locations will be taken into account when tables are placed in the spring. – Done
- Ground surface under the tables are not firm, stable and level
- Exploring possibility of purchasing accessible swings. In Progress

MEDIUM TERM

- No sensory components, such as gardens or planters
- No ground level stand-alone features, such as spring rockers or teeter-totters
- Walkway to playground area is not stable and firm
- No designated parking spaces

LONG TERM

No items for this category

Club House Playground – NOT MUNICIPAL PROPERTY

- No sensory components, such as gardens or planters
- No designated parking spaces
- No waste receptacle on-site
- Picnic tables on site are not accessible.