

Assessment of Playgrounds

Lesla and Misty

Brass Hill Playground

- No sensory components, such as gardens or planters
- No ground level stand-alone features, such as spring rockers or teeter-totters

- No designated parking area

- Waste receptacle should be color-contrasted with surroundings.

- Picnic tables on site are not accessible.
- No clear accessible path up to the table

Barrington Playground

- No clearly defined accessible entrance

- No sensory components, such as gardens or planters
- No ground level stand-alone features, such as spring rockers or teeter-totters

- Open gravel parking lot
- No designated parking spaces

- Waste receptacle should be color-contrasted with surroundings.
- Waste receptacles are not accessible

- Picnic tables on site are not accessible.
- No clear accessible path up to the table

Sherose Island Playground

- Walkway leading to playground requires attention (uneven surface, narrow, directional signs required from parking lot, surface blends with surroundings)

- No sensory components, such as gardens or planters

- 1 accessible parking space requires repainting

- Waste receptacle should be color-contrasted with surroundings.

- Picnic tables on site are not accessible.
- No clear accessible path up to the table

South Side Playground

- No sensory components, such as gardens or planters
- No ground level stand-alone features, such as spring rockers or teeter-totters
- Walkway to playground area is not stable and firm
- Open gravel parking lot
- No designated parking spaces
- No waste receptacle on-site
- Picnic tables on site are not accessible.
- No clear accessible path up to the table
- Ground surface under the tables are not firm, stable and level

Club House Playground

- No sensory components, such as gardens or planters
- Open gravel parking lot
- no designated parking spaces
- No waste receptacle on-site
- Picnic tables on site are not accessible.